

Operator: EXTRACTION OIL & GAS INC
Location Name: HSR-TR RANCH-62S66W 3SESE
Loc ID: 320407
Inspection: 709400092



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E

CA: Weeds were observed throughout the reclaimed areas of the site. Operator has failed to control and manage weeds to prevent weed waste and prevent seeds from spreading onto adjacent lands. Comply with Rule 606.c.

CA Resolution: Weeds were removed/mowed on 4/12/2023. The location now complies with Rule 606.c.