

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 112-27 Pad

Location ID: 324045



Photo # 5964 From entrance to location




Photo # 5967 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: TEP ROCKY MOUNTAIN LLC RMV 112-27 Pad**  
**Location ID: 324045**



**Photo # 5968 Location**




**Photo # 5969 Location**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 112-27 Pad

Location ID: 324045



**Photo # 5970 Meter calibration info not conspicuously posted**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources