

# Interim and Stormwater Inspection

April 5, 2023

Operator: Crestone Peak , #10633

Location ID: 319014

Inspection Document #:709400134

Weld, CO

NWNW, Section 34, 1N67W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources



Photo 1. Photo taken of location sign at tank battery on location.



Inspection Photos  
Location Name: Genemeyer Wagner C1  
Location ID: 319014



**Photo 2. Photo taken facing north of stormwater leaving site causing reeling**



**Photo 3. Photo taken facing southwest of stormwater leaving site causing reeling**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 709400134