

Final Reclamation Inspection

April 20, 2023

Operator: HIGHPOINT OPERATING CORPORATION - #10071

Location ID: 331623

Inspection Document #: 697504608

Weld County, CO

NENW Section 28 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DOW-LAURA #3-28
Location ID: 331623



Photo 1. COGCC GISOnline aerial imagery from 2021. This inspection only covers the well location. The access road and tank battery are being addressed under a separate inspection (FIR Doc.#697504606).



Inspection Photos
Location Name: DOW-LAURA #3-28
Location ID: 331623



Photo 2. Photo taken from the well location, facing North. Photo illustrates the location consists mostly of weeds with little to no perennial vegetation that is not reflective of reference areas.



Photo 3. Photo taken from the well location, facing West. See comments under Photo 2.



Inspection Photos
Location Name: DOW-LAURA #3-28
Location ID: 331623



Photo 4. Reference photo taken adjacent to the well location, facing North.