

Final Reclamation Inspection

April 20, 2023

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 331413

Inspection Document #: 697504610

Weld County, CO

SWNE Section 28 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DOW #32-28
Location ID: 331413



Photo 1. COGCC GISOnline aerial imagery from 2015. This inspection covers the well location, access roads and tank battery.





Photo 2. Photo taken from a portion of the main access road, facing Southeast. Photo illustrates the access road is bare with no perennial vegetation that is not reflective of reference areas.



Photo 3. Close up photo taken from a portion of the main access road, illustrating the lack of any vegetation.

Inspection Photos
Location Name: DOW #32-28
Location ID: 331413



Photo 4. Photo taken from the offsite tank battery location, facing North. Photo illustrates the location consists mostly of weeds with little perennial vegetation that is not reflective of reference areas.



Photo 5. Photo taken from the offsite tank battery location, facing West. Photo illustrates more of the failed access road.



Photo 6. Photo taken from a portion of the well location access road, facing South. Photo illustrates the location consists mostly of weeds with little perennial vegetation that is not reflective of reference areas. It also appears to not all the gravel was removed.



Photo 7. Photo taken from the well location, facing North. See comments under Photo 6.

Inspection Photos
Location Name: DOW #32-28
Location ID: 331413



Photo 8. Reference photo taken from one of the nearby well locations.