

Final Reclamation Inspection

April 20, 2023

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 305671

Inspection Document #: 697504612

Weld County, CO

SENE Section 28 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: LAURA #8-28
Location ID: 305671



Photo 1. COGCC GISOnline aerial imagery from 2015. This inspection covers the well location/tank battery and access roads.



Inspection Photos
Location Name: LAURA #8-28
Location ID: 305671



Photo 2. Photo taken from a portion of the main access road, facing West. Photo illustrates the access road is bare with no perennial vegetation that is not reflective of reference areas.



Photo 3. Photo taken from the well/tank battery location, facing West. Photo illustrates the location consists mostly of weeds with little perennial vegetation that is not reflective of reference areas.

Inspection Photos
Location Name: LAURA #8-28
Location ID: 305671



Photo 4. Photo taken from the well/tank battery location, facing South. See comments under Photo 3.



Photo 5. Photo taken from the well/tank battery location, facing East. See comments under Photo 3.

Inspection Photos
Location Name: LAURA #8-28
Location ID: 305671



Photo 6. Reference photo taken adjacent from the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697504612