

Final Reclamation Inspection

April 20, 2023

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 415157

Inspection Document #: 697504621

Weld County, CO

NWSW Section 28 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DOW 13-28
Location ID: 415157



Photo 1. COGCC GISOnline aerial imagery from 2015. This inspection covers the well location and access road. The associated tank battery (red x) will be addressed under a separate inspection.



Photo 2. Photo taken from a portion of the access road, facing South. Photo illustrates the access road consists mostly of weeds that is not reflective of reference areas.



Photo 3. Photo taken from the well location, facing West. Photo illustrates the location consists mostly of weeds that is not reflective of reference areas.

Inspection Photos
Location Name: DOW 13-28
Location ID: 415157



Photo 4. Photo taken from the well location, facing North. See comments under Photo 3.



Photo 5. Photo taken from the well location, facing East. Reference vegetation is in the background (i.e., green vegetation).