

# Final Reclamation Inspection

April 20, 2023

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 331805

Inspection Document #: 697504629

Weld County, CO

NENE Section 33 T5N R63W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DOW #41-33  
Location ID: 331805



**Photo 1.** COGCC GISOnline aerial imagery from 2015. This inspection covers the well location, offsite tank battery and access road.

Inspection Photos  
Location Name: DOW #41-33  
Location ID: 331805



**Photo 2.** Photo taken from the tank battery location and access road, facing West. Photo illustrates the tank battery and access road are mostly bare that is not reflective of reference areas.



**Photo 3.** Photo taken from the tank battery location, facing South. See comments under Photo 2.

Inspection Photos  
Location Name: DOW #41-33  
Location ID: 331805



**Photo 4.** Photo taken from the tank battery location, facing East. See comments under Photo 2.



**Photo 5.** Photo taken from the well location, facing South. See comments under Photo 2.

Inspection Photos  
Location Name: DOW #41-33  
Location ID: 331805



**Photo 6.** Photo taken from the well location, facing North. See comments under Photo 2.



**Photo 7.** Photo taken from the well location, facing West. See comments under Photo 2.