

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 522-27 Pad

Location ID: 335128



Photo # 6038 From entrance to location



Photo # 6039 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 522-27 Pad

Location ID: 335128



Photo # 6040 Location



Photo # 6041 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 522-27 Pad

Location ID: 335128



Photo # 6042 Location



Photo # 6050 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 522-27 Pad

Location ID: 335128



Photo # 3566 From Inspection 708900188 on 03/28/2023

Meter calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources