

CAERUS PICEANCE LLC, PUCKETT-66S96W/31SENW

Location # 335297



**Wellhead Entrance/Site Degradation/Slope Erosion
– Photo #02422**



Inadequate Erosion Control – Photo #02423



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

CAERUS PICEANCE LLC, PUCKETT-66S96W/31SENW

Location # 335297



Inadequate Erosion Control – Photo #02425



Site Degradation/Transport of Sediment – Photo #02424

CAERUS PICEANCE LLC, PUCKETT-66S96W/31SENW

Location # 335297



Separator & Tank Battery Entrance – Photo #02427



Storage of Unused Supplies/Equipment – Photo #02431

CAERUS PICEANCE LLC, PUCKETT-66S96W/31SENW

Location # 335297



**Access Road Degradation/Transport of Sediment –
Photo #02432**



Inadequate Vehicle Tacking BMPs – Photo #