

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 203-20 Pad

Location ID: 323961



Photo # 6000 From entrance to location



Photo # 6001 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 203-20 Pad

Location ID: 323961



Photo # 6002 Location



Photo # 6003 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 203-20 Pad

Location ID: 323961



Photo # 6004 Location



Photo # 6006 Meter calibration info not conspicuously posted



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources