

Inspection Photos

Loc: 424701

Operator: MARALEX RESOURCES INC

Inspection Date: 4/18/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 424701 | Date: 4/18/2023

Inspection Photos



Photo 1. Facing northwest toward the wellsite. There is an open hole next to the second well at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 424701 | Date: 4/18/2023

Inspection Photos



Photo 2. There is a deep hole next to this wellhead that needs to be immediately covered to prevent entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 424701 | Date: 4/18/2023

Inspection Photos



Photo 3. Facing northeast toward the multi well site.



Inspection Photos



Photo 4. Facing north along the west side of the location. There are noxious weeds beginning to sprout up that will need to be controlled. Red arrow → Musk thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 424701 | Date: 4/18/2023

Inspection Photos



Photo 5. There is a pile of weed debris at the northeast side of the location that needs to be removed. Weed debris along the fence line also needs to be cleaned up and removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 424701 | Date: 4/18/2023