

Inspection Photos
Location Name: Federal Paint 9-26
Location ID: 332372



Photo 1 – Concrete Blocks



Photo 2 – Heater Treater and Wellhead

Inspection Photos
Location Name: Federal Paint 9-26
Location ID: 332372



Photo 3 – No Final Reclamation appears to have been started



Photo 4 – No Final Reclamation appears to have been started

Inspection Photos
Location Name: Federal Paint 9-26
Location ID: 332372



Photo 5 – No Final Reclamation appears to have been started



Photo 6 – Wellhead Sign

Inspection Photos
Location Name: Federal Paint 9-26
Location ID: 332372



**Photo 7 – Night Cap – Well appears to have been Plugged
and Abandoned**