

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 313-16 Pad

Location ID: 335453



Photo # 6157 From entrance to location




Photo # 6158 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 313-16 Pad

Location ID: 335453



Photo # 6160 Chemical containment 1/2 - 2/3 full/Failure to maintain chemical BMP



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources