

Inspection Photos
Location Name: Jolly Platts#1
Location ID:319643



Photo#1 Production Tanks

Photo#2 (3) Separators/ECD/Propane Tank

Inspection Photos
Location Name: Jolly Platts#1
Location ID:319643



Photo#3 Produced Water Tank/**NO Top over opening**

Photo# **Appears to be hydrocarbons in the first inert pit**

Inspection Photos
Location Name: Jolly Platts#1
Location ID:319643



Photo#5 Appears to be hydrocarbons in the first inert pit

Photo#6 Appears to be hydrocarbons in the first inert pit

Inspection Photos
Location Name: Jolly Platts#1
Location ID:319643



Photo#7 Inert Pit

Photo#8 Pumpjack/Wellhead