

Inspection Photos  
Location Name: Martin T Hart G1  
Location ID: 318226



Photo 1 WH sign.

Photo 2 WH.

**Inspection Photos**  
**Location Name: Martin T Hart G1**  
**Location ID: 318226**



**Photo 4 Pump Jack.**



**Photo 4 ancillary equipment .**



**Inspection Photos**  
**Location Name: Martin T Hart G1**  
**Location ID: 318226**



**Photo 5 TB sign.**



**Photo 6 TB.**

**Inspection Photos**  
**Location Name: Martin T Hart G1**  
**Location ID: 318226**



**Photo 7 Vertical separators, aux pump and flow line manifold.**



**Photo 8 Horizontal Heater Treater.**



**Inspection Photos**  
**Location Name: Martin T Hart G1**  
**Location ID: 318226**



**Photo 9 Stained soil in Heater Treater housing.**



**Photo 10 Stained soil in Horizontal Heater Treater housing.**

