

# Interim Reclamation and Stormwater Inspection

Date: 04/19/2023

Operator: CIVITAS NORTH LLC - 10661

Location ID: 454627

Inspection Document #: 708200160

Weld County, CO

Lot 3 Section 6 T8N R60W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Hunt Fed 8-60 6A  
Location ID: 454627



**Photo 1.** Facing north near the entrance. Interim areas do not appear to be progressing towards reclamation standards with little desirable plant species evident and large areas of bare soil. Additional reclamation activities will need to be performed to meet Rule 1003 standards.

Inspection Photos  
Location Name: Hunt Fed 8-60 6A  
Location ID: 454627



Photo 2. Facing northeast near the northeast corner. See comments in Photo 1.

Inspection Photos  
Location Name: Hunt Fed 8-60 6A  
Location ID: 454627



Photo 3. Facing north from the center/eastern portion. See comments in Photo 1.

Inspection Photos  
Location Name: Hunt Fed 8-60 6A  
Location ID: 454627



**Photo 4.** Facing north towards topsoil stockpile (outlined in red). See comments in Photo 1.

Inspection Photos  
Location Name: Hunt Fed 8-60 6A  
Location ID: 454627



Photo 5. Facing west towards the southwest corner. See comments in Photo 1.

Inspection Photos  
Location Name: Hunt Fed 8-60 6A  
Location ID: 454627



**Photos 6 & 7.** Unused equipment/storage of equipment; items need to be removed as storage on location is prohibited.

Inspection Photos  
Location Name: Hunt Fed 8-60 6A  
Location ID: 454627



**Photos 8 & 9.** Tumbleweed accumulations within and around equipment needs to be removed as it presents a fire hazard.

Inspection Photos  
Location Name: Hunt Fed 8-60 6A  
Location ID: 454627




**Photo 10.** Red outline illustrates production area that needs to be reclaimed. See additional comments in Photo 12.

Inspection Photos  
Location Name: Hunt Fed 8-60 6A  
Location ID: 454627



Photo 11. See comments in Photos 10 & 12.

Inspection Photos  
Location Name: Hunt Fed 8-60 6A  
Location ID: 454627



**Photo 12.** Red outline illustrates production areas that are not currently being used and require additional interim reclamation activities to reclaim approximately 1.8 acres. 7 wells were permitted (green line) and never drilled; permits are now expired.