

Interim Reclamation and Stormwater Inspection

Date: 04/20/2023

Operator: IMPETRO RESOURCES LLC - 10690

Location ID: 317362

Inspection Document #: 708200180

Washington County, CO

NENW Section 12 T3S R50W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Christianson-63S50W
Location ID: 317362



4/20/23, 11:43 AM
258° W
COGCC

Photo 1. Interim areas appear to be reflective of reference areas at the time of this inspection. Production areas also appear to be stabilized with no evidence of stormwater/erosion issues.

Inspection Photos
Location Name: Christianson-63S50W
Location ID: 317362



Photo 2. Stained soil near wellhead had chemical odor and will need to be properly disposed of per Rule 905.e.

Inspection Photos
Location Name: Christianson-63S50W
Location ID: 317362



Photo 3. Stained soil at wellhead will need to be properly cleaned up per Rule 905.e.



Photo 4. Close-up of day tank near wellhead. Photo illustrates unused equipment and no wildlife netting installed around secondary containment.