

Interim Reclamation and Stormwater Inspection

Date: 04/20/2023

Operator: IMPETRO RESOURCES LLC - 10690

Location ID: 317363

Inspection Document #: 708200185

Washington County, CO

SWNW Section 12 T3S R50W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Christianson SWD-63S50W
Location ID: 317363



Photo 1. Stained soil will need to be properly cleaned up and disposed of per Rule 905.e. Additionally, unknown substance originating from wellhead will need to be properly disposed of and mechanical conditions will need to be inspected/maintained per Rule 608.e.

Inspection Photos
Location Name: Christianson SWD-63S50W
Location ID: 317363



Photo 2. Overview of interim areas that are not progressing towards reclamation standards (e.g poor growth and vehicle tracks evident). Operator shall make attempts to limit excessive vehicle tracks.

Inspection Photos
Location Name: Christianson SWD-63S50W
Location ID: 317363



Photo 3. Facing northwest; see comments in Photo 2.

Inspection Photos
Location Name: Christianson SWD-63S50W
Location ID: 317363



Photo 4. Reference area photo taken south of well.