

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/20/2023

Submitted Date:

04/21/2023

Document Number:

697504612

FIELD INSPECTION FORMLoc ID 305671 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		chase.reed@state.co.us	
,		inspections@civiresources.com	
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280955	WELL	PA	07/03/2019	GW	123-23332	LAURA 8-28	RI
447085	TANK BATTERY	AC	07/29/2016		-	LAURA-65N63W 28SENE	RI
447086	TANK BATTERY	AC	07/29/2016		-	LAURA-65N63W 28SENE	RI

General Comment:

On 4/20/2023, Reclamation Specialist Chris Binschus performed an inspection in response to a complaint regarding failed reclamation throughout the Centennial Valley SWA. Refer to the Complaint, Reclamation, and COGCC Comments sections of this inspection report for additional details.

Inspected FacilitiesFacility ID: 280955 Type: WELL API Number: 123-23332 Status: PA Insp. Status: RIFacility ID: 447085 Type: TANK API Number: - Status: AC Insp. Status: RIFacility ID: 447086 Type: TANK API Number: - Status: AC Insp. Status: RI**Complaint**

Comment: [Complaint: # 403379491](#)
[Field Inspector Assigned: Chris Binschus](#)
[Location ID: #305671](#)
[Inspection Document: #697504612](#)
Nature of complaint: CPW had concerns about failed reclamation that was previously performed by Bonanza Creek approximately three years ago.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded Pass Contoured Pass Culverts removed Pass

Gravel removed Fail

Location and associated production facilities reclaimed Fail Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% Fail Cropland: perennial forage _____

Weeds present Fail Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

The well/tank battery location consisted mostly of weeds with little perennial vegetation that is not reflective of reference areas. Bare soil was more prevalent along the main access road. Refer to the attached photos.

Due to the lack of desirable vegetation establishment, COGCC is requiring soil sampling. Operator shall take samples along portions of the failed reclamation and background reference samples for comparison. Operator shall take discrete samples at six (6) inches intervals to a minimum depth of two (2) feet. See COGCC Comments Section for details on analytics.

Note- Operator may need to install temporary fencing to facilitate on-going grazing operations.

Corrective Action:

Comply with Rule 1004 to conduct additional reclamation. The corrective action date is the date the location was observed out of compliance.

Date **04/20/2023**

For soil samples, submit results via Form 4 Sundry Notice to the attention of Chris Binschus no later than two weeks after receiving results. Soil samples shall be overlaid on an aerial map depicting where soil sample locations and reference samples were taken.

Overall Final Reclamation

FailWell Release on Active Location ☐Multi-Well Location ☐**COGCC Comments**

Comment	User	Date
<p>Below is the required soil sampling:</p> <ul style="list-style-type: none"> pH, electrical conductivity (EC), SAR, and Boron (methods per the Table 915-1; all values rounded to the nearest 0.10); organic matter (Walkely-Black method); nitrate, ammonium nitrogen, phosphorus, potassium, zinc, iron, manganese, copper, and chloride (all using AD-DTPA extraction); lime and texture estimates; percent calcium carbonate equivalency (gravimetric); texture (hydrometer with textures reported as USDA) 	binschusc	04/21/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403381134	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6090366
697504613	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6090356