

TEP
McPherson A
Location # 335539



Production equipment



Production equipment



TEP
McPherson A
Location # 335539



Pig station



Staining

TEP
McPherson A
Location # 335539



Staining



Staining

TEP
McPherson A
Location # 335539



Staining and debris



Debris

TEP
McPherson A
Location # 335539



Staining



Debris

TEP
McPherson A
Location # 335539



Follow up inspection of secondary containment still not repaired



Follow up inspection of secondary containment still not repaired




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
McPherson A
Location # 335539



Previous inspection photo of secondary containment



Debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
McPherson A
Location # 335539



Stored equipment appears to have pumps set since previous inspection but still not in service.



Previous inspection photo of stored equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources