

# Interim Reclamation and Stormwater Inspection

Date: 04/20/2023

Operator: ST CROIX OPERATING INC - 81490

Location ID: 317392

Inspection Document #:

Washington County, CO

NWNE Section 11 T3S R50W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Young SWD  
Location ID: 317392



**Photo 1.** Facing north from location. The location will require further reclamation activities as portions of the interim areas consist of bare/exposed soils (outlined in red). It was evident that recent a disturbance occurred on the location, possibly berm repairs, and subsequent reclaim should follow to ensure soils are properly stabilized with vegetation.



Inspection Photos  
Location Name: Young SWD  
Location ID: 317392



**Photo 2.** See comments in Photo 1.



Inspection Photos  
Location Name: Young SWD  
Location ID: 317392



**Photo 3.** South side of tank battery; see comments in Photo 1.



Inspection Photos  
Location Name: Young SWD  
Location ID: 317392



4/20/23, 11:20 AM  
58° NE  
COGCC

**Photo 4.** Guy line anchors not properly marked per Rule 603.j



Inspection Photos  
Location Name: Young SWD  
Location ID: 317392



**Photo 5.** See comments in Photo 4.