

Inspection Photos
Simcoe LLC. Schofield A1
API 067-07859



Photo #1. Overview of well location.

Inspection Photos
Simcoe LLC. Schofield A1
API 067-07859




Photo #2. Produced water tank containment missing label.

Inspection Photos
Simcoe LLC. Schofield A1
API 067-07859



Photo #3. Lube oil leak/spill and Impacted material.