

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location # 334269



Location Entrance – Photo #02616



Production Equipment/Weeds – Photo #02617

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location # 334269



Tank Battery/Weeds – Photo #02620



Production Equipment/Weeds – Photo #02621

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location # 334269



Tank Battery/Weeds – Photo #02622



Unused Equipment – Photo #02619

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location # 334269



Location Lacks Stabilization – Photo #02625



Insufficient Vehicle Tracking BMP at Location Entrance/Exit – Photo #02626