

Inspection Photos

Location Name: WEST IRRIGATION-USX AB-67N64W/33SWSE

Location #: 306369



Photo #1

West Irrigation-USX AB 33-15 (123-24545) Wellsite
Temporarily Abandoned | TA



Photo #2

West Irrigation USX AB 33-15, 33-23 Battery site
Inactive | Shut-down
Formerly served West Irrigation-USX AB 33-10;
Plugged & Abandoned | PA

Inspection Photos

Location Name: WEST IRRIGATION-USX AB-67N64W/33SWSE

Location #: 306369



Photo #3

West Irrigation USX AB 33-15, 33-23 Battery site

Inactive | Shut-down

Tank(s): SE corner



Photo #4

West Irrigation USX AB 33-15, 33-23 Battery site

Inactive | Shut-down

Separator(s), ECD(s)

Inspection Photos

Location Name: WEST IRRIGATION-USX AB-67N64W/33SWSE

Location #: 306369



Photo #5

West Irrigation USX AB 33-15, 33-23 Battery site

Inactive | Shut-down

Battery sign(s)



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources