

CAERUS PICEANCE LLC, COWPERTHWAITTE-68S97W/6SWNW

Location # 322458




Location – Photo #02651

Location – Photo #02652

CAERUS PICEANCE LLC, COWPERTHWAITTE-68S97W/6SWNW

Location # 322458



Location – Photo #02658

Wellhead – Photo #02653

CAERUS PICEANCE LLC, COWPERTHWAITTE-68S97W/6SWNW

Location # 322458



Separator – Photo #02656



Tank Battery – Photo #02654

CAERUS PICEANCE LLC, COWPERTHWAITTE-68S97W/6SWNW

Location # 322458



Pig Station – Photo #02657



Gravel BMP Installed to Minimize Sediment Transportation – Photo #02659