

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403341937

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>ANSCHUTZ EXPLORATION CORP</u>	Operator No: <u>3104</u>	Phone Numbers
Address: <u>555 17TH ST STE 2400</u>		Phone: <u>(303) 299-1599</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Schuyler Hamilton</u>	Email: <u>schuyler.hamilton@aec-denver.com</u>	Mobile: <u>(720) 925-1820</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 23348 Initial Form 27 Document #: 403056825

PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☒ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☐ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: _____

SITE INFORMATION

☐ Yes ☐ Multiple Facilities

Facility Type: <u>LOCATION</u>	Facility ID: <u>315979</u>	API #: _____	County Name: <u>RIO BLANCO</u>
Facility Name: <u>PRF-63N97W 21NESE</u>		Latitude: <u>40.212478</u>	Longitude: <u>-108.276409</u>
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>NESE</u>	Sec: <u>21</u>	Twp: <u>3N</u>	Range: <u>97W</u>
Meridian: <u>6</u>		Sensitive Area? <u>Yes</u>	
Facility Type: <u>SPILL OR RELEASE</u>	Facility ID: <u>481972</u>	API #: _____	County Name: <u>RIO BLANCO</u>
Facility Name: <u>PRF C-1W</u>		Latitude: <u>40.212620</u>	Longitude: <u>-108.276390</u>
** correct Lat/Long if needed: Latitude: <u>40.212630</u>		Longitude: <u>-108.276100</u>	
QtrQtr: <u>NESE</u>	Sec: <u>21</u>	Twp: <u>3N</u>	Range: <u>97W</u>
Meridian: <u>6</u>		Sensitive Area? <u>Yes</u>	

SITE CONDITIONS

General soil type - USCS Classifications ML

Most Sensitive Adjacent Land Use Rangeland

Is domestic water well within 1/4 mile? No

Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Unnamed surface water is present 250 feet to the northeast of the Location.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- ☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste
- ☒ Produced Water ☐ Workover Fluids
- ☐ Oil ☐ Tank Bottoms
- ☐ Condensate ☐ Pigging Waste
- ☐ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	To be determined	Laboratory analysis of soil samples

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

On March 27, 2022, an unknown volume of produced water overflowed from a tank and was spilled inside secondary containment. The release was reported via Form 19 Document 403000387 and was assigned Spill/Release Point ID 481972. Form 27 Document 403056825 was later submitted to open Remediation Project Number 23348. Please reference Form 27 Document 403068552 for initial response and spill characterization details.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

- ☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Additional soil samples will be collected as needed to delineate the vertical extent of total petroleum hydrocarbon (TPH) soil impacts beneath secondary containment when weather conditions and natural resource stipulations are suitable for conducting further investigation. Additional background soil samples will be collected to characterize native levels of various inorganic constituents of concern at depth. Soil samples will be submitted for the approved reduced analyte list of TPH, pH, sodium adsorption ratio (SAR), and arsenic. See the attached Proposed Investigation Site Diagram for details regarding proposed site investigation. Site investigation is scheduled for July 2023.

Proposed Groundwater Sampling

- ☐ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Groundwater is not anticipated to be encountered during site investigation. If groundwater is encountered, a characterization sample will be collected and analyzed.

Proposed Surface Water Sampling

- ☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

- ☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 31

Number of soil samples exceeding 915-1 31

NA / ND

-- Highest concentration of TPH (mg/kg) 4414

-- Highest concentration of SAR 70.2

Was the areal and vertical extent of soil contamination delineated? No

BTEX > 915-1 No

Approximate areal extent (square feet) 5000

Vertical Extent > 915-1 (in feet) 25

Groundwater

Number of groundwater samples collected 0

Highest concentration of Benzene (µg/l)

Was extent of groundwater contaminated delineated? Yes

Highest concentration of Toluene (µg/l)

Depth to groundwater (below ground surface, in feet)

Highest concentration of Ethylbenzene (µg/l)

Number of groundwater monitoring wells installed

Highest concentration of Xylene (µg/l)

Number of groundwater samples exceeding 915-1

Highest concentration of Methane (mg/l)

Surface Water

1 Number of surface water samples collected

0 Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☒ Were background samples collected as part of this site investigation?

On September 28, 2022, five soil samples were collected from nearby, native, non-impacted soil. See the Report of Work Completed (ROWC) associated with Form 27 Document 403215682 for details.

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☒ Is further site investigation required?

Additional soil sampling and delineation in accordance with Rule 913.b.(2). Delineation will be completed in July 2023 when weather conditions are suitable for conducting further delineation under secondary containment and the location. Upon completing delineation, in-situ and ex-situ remediation strategies will be evaluated and proposed in a supplemental Form 27.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Remediation strategies will be evaluated following delineation of identified impacts. The selected remedial approach will be presented in a Supplemental Form 27.

REMEDIAL ACTION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Initial site investigation efforts were completed on May 10, 2022. Eight soil samples were collected at the Location from the point of release (POR) and from visibly saturated areas of the pad surface. Analytical results of initial soil samples indicated exceedances of COGCC Table 915-1 Residential Screening Levels for total petroleum hydrocarbons (TPH), pH, sodium adsorption ratio (SAR), and arsenic. Two surface water samples and one waste water characterization sample were also collected during initial site investigation. On July 25, 2022, drilling activities were conducted to delineate the extents of identified soil impacts. A total of 18 soil samples were collected from ten soil borings advanced using a direct push drill rig. Collected samples were packed on ice and delivered to a laboratory for analysis of the approved reduced suite of TPH, pH, SAR, and arsenic. Laboratory results of the borehole samples indicate compliance with COGCC Table 915-1 Residential Soil Screening Levels except for SAR, pH, and arsenic.

On September 28, 2022, additional investigation was performed to delineate the extent of soil impacts within secondary containment. Three soil borings were advanced with a hand auger to delineate the vertical extent of soil impacts beneath secondary containment. Five soil samples were collected from the borings. Laboratory results of the soil samples exceed COGCC Table 915-1 Residential Soil Screening Levels for TPH, SAR, pH, and arsenic. Laboratory results of background samples collected on September 28, 2022, exceed COGCC Table 915-1 Residential Soil Screening Levels for pH and arsenic. See the ROWC associated with Form 27 Document 403215682 for details.

Soil Remediation Summary

☐ In Situ

☐ Ex Situ

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

_____ Excavate and offsite disposal
_____ If Yes: Estimated Volume (Cubic Yards) _____
_____ Name of Licensed Disposal Facility or COGCC Facility ID # _____
_____ Excavate and onsite remediation
_____ Land Treatment
_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater is not anticipated to be encountered during site investigation activities.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

☒ Quarterly☐ Semi-Annually☐ Annually☐ Other

☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:

☐ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☒ Other Q1 2023 Status Update

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Anticipated cost for delineation with an environmental drilling rig are entered below.

Operator anticipates the remaining cost for this project to be: \$ 23000

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No _____

If YES:

☐ Compliant with Rule 913.h.(1).☐ Compliant with Rule 913.h.(2).☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? _____

Does the previous reply indicate consideration of background concentrations? _____

Does Groundwater meet Table 915-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the COGCC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Any disturbance of the pad surface will be returned to the active working surface of the location for continued operation. When the site is decommissioned at a later date, it will be reclaimed in accordance with 1000 Series regulations.

Is the described reclamation complete? No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim

☐ Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, or date of discovery. 03/27/2022

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 03/27/2022

Proposed site investigation commencement. 05/10/2022

Proposed completion of site investigation. _____

REMEDIAL ACTION DATES

Proposed start date of Remediation. _____

Proposed date of completion of Remediation. _____

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☐ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

This form has been submitted to satisfy the Q1 2023 quarterly reporting requirement for Remediation Project Number 23348. Please find the attached Proposed Investigation Site Diagram for details regarding further site investigation.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Schuyler Hamilton

Title: Env Compliance Specialist

Submit Date: _____

Email: schuyler.hamilton@aec-denver.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

Remediation Project Number: 23348

COA Type**Description**

0 COA	

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

403388785	SITE INVESTIGATION PLAN
-----------	-------------------------

Total Attach: 1 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)