

# Inspection Photos

API: 071-08651

Operator: OGRIS OPERATING LLC

Inspection Date: 5/1/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08651 | Date: 5/1/2023

## Inspection Photos



**Photo 1.** Facing southwest toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08651 | Date: 5/1/2023

## Inspection Photos



**Photo 2.** There is some trash off the east side of the pad.



## Inspection Photos



**Photo 3.** There is oily fluid in the engine skid that needs to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08651 | Date: 5/1/2023

## Inspection Photos



**Photo 4.** Sign does not have current operator info posted.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08651 | Date: 5/1/2023