

Final Reclamation Inspection

April 27, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 332073

Inspection Document #: 697504638

Weld County, CO

SWNE Section 30 T6N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: J&L FARMS #32-30
Location ID: 332073



Photo 1. Photo taken from the western portion of the tank battery, facing West. Photo illustrates the Operator has failed to perform final reclamation at the tank battery (gravel present) and failed to respond to the previous corrective action.



Photo 2. Photo taken from the eastern portion of the tank battery, facing East. Photo illustrates the current condition does not appear to have changed since the previous inspection.

Inspection Photos
Location Name: J&L FARMS #32-30
Location ID: 332073



Photo 3. Photo taken from the well location, facing West. Photo illustrates the current condition does not appear to have changed since the previous inspection.



Photo 4. Photo taken from the well location, facing South. See comments under Photo 3.

Inspection Photos
Location Name: J&L FARMS #32-30
Location ID: 332073



Photo 5. 2021 aerial imagery illustrates the well location and associated offsite tank battery.