

Inspection Photos
Location Name: F Quarter Circle #1
Location ID: 327148



Photo 1 – Tank Battery – Capacity Label Faded

Photo 2 – Tank Battery Signs

Inspection Photos
Location Name: F Quarter Circle #1
Location ID: 327148



Photo 3 – Unmarked Riser in Tank Berm



Photo 4 – Heater Treater

Inspection Photos
Location Name: F Quarter Circle #1
Location ID: 327148



Photo 5 – Stained Soil at Drain Valves at Back side on Tank

Photo 6 – Temp Water Tank – No Berm

Inspection Photos
Location Name: F Quarter Circle #1
Location ID: 327148



Photo 7 – Sales Line Locked Out/Tagged Out by Sales Operator

Photo 8 – Gas Meter House

Inspection Photos
Location Name: F Quarter Circle #1
Location ID: 327148



Photo 9 – Pumping Unit



Photo 10 – Propane Tank

Inspection Photos
Location Name: F Quarter Circle #1
Location ID: 327148



Photo 11 – Propane Tank

Photo 12 – Well Sign

Inspection Photos
Location Name: F Quarter Circle #1
Location ID: 327148



Photo 13 – Wellhead