

Inspection Photos
Location Name: Vera #1
Location ID: 318556




Photo 1 – Unmarked Risers at Separator



Photo 2 – Unmarked Risers at Separator

Inspection Photos
Location Name: Vera #1
Location ID: 318556



Photo 3 – Gas Meter – LOTO by Sales Operator DCP



Photo 4 – Gas Meter – LOTO by Sales Operator D

Inspection Photos
Location Name: Vera #1
Location ID: 318556



Photo 5 – Tank Battery Sign



Photo 6 – NFPA Label on Produced Water

Inspection Photos
Location Name: Vera #1
Location ID: 318556



Photo 7 – Crude Oil Tank



Photo 8 – Pumping Unit

Inspection Photos
Location Name: Vera #1
Location ID: 318556



Photo 9 – Wellhead



Photo 10 – Gas Engine