

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC VASSAR HEATH 130 Pad

Location ID: 322425



May 2, 2023 at 10:00:38 AM



May 2, 2023 at 10:01:02 AM

Photo # 6714 From entrance to location

Photo # 6715 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC VASSAR HEATH 130 Pad

Location ID: 322425



Photo # 6716 Location



Photo # 6717 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC VASSAR HEATH 130 Pad

Location ID: 322425



Photo # 3477 From Inspection 708900168 conducted on 03/27/2023 Meter calibration info not conspicuously posted



Photo # 6719 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC VASSAR HEATH 130 Pad

Location ID: 322425




Photo # 3478 From Inspection 708900168 conducted on 03/27/2023 Meter calibration info not conspicuously posted



Photo # 6718 Meter calibration info not conspicuously posted