

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Photo # 6739 From entrance to location

Photo # 6740 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Photo # 6741 Location

Photo # 6742 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Photo # 6743 Location



Photo # 6748 Unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 26-21 Pad

Location ID: 323917



Photo # 3311 From Inspection 708900166 conducted on 03/24/2023 Meter calibration info not conspicuously posted



Photo # 6747 Meter calibration info not conspicuously posted