

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-29 Pad

Location ID: 335076



Photo # 6658 From entrance to location



Photo # 6659 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-29 Pad

Location ID: 335076



Photo # 6660 Location



Photo # 6661 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-29 Pad

Location ID: 335076



May 2, 2023 at 8:45:14 AM  
CO



May 2, 2023 at 8:59:37 AM  
CO

Photo # 6662 Location

Photo # 6674 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-29 Pad

Location ID: 335076



Photo # 2327 From Inspection 708900108 conducted on 03/13/2023 Meter calibration info not conspicuously posted

Photo # 6679 Meter calibration info not conspicuously posted

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-29 Pad

Location ID: 335076



Photo # 2326 From Inspection 708900108 conducted on 03/13/2023 Meter calibration info not conspicuously posted

Photo # 6680 Meter calibration info not conspicuously posted

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 22-29 Pad

Location ID: 335076



Photo # 2325 From Inspection 708900108 conducted on 03/13/2023 Meter calibration info not conspicuously posted



Photo # 6681 Meter calibration info not conspicuously posted