

Final Reclamation Inspection

April 27, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 305495

Inspection Document #: 697504654

Weld County, CO

SENW Section 3 T6N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CORNISH #22-3
Location ID: 305495



Photo 1. Photo taken from the well location, facing South. Photo illustrates the well location is mostly bare ground and weedy, annual vegetation.



Photo 2. Photo taken from the well location, facing South. Photo is illustrating the well location was seeded with the evidence of drill rows but no germination.

Note- well location access road remains due to TA'ed wells from another Operator (Noble).

Inspection Photos
Location Name: CORNISH #22-3
Location ID: 305495



Photo 3. Photo taken from the well location, facing North. See comments under Photo 1.



Photo 4. Photo taken from the associated offsite tank battery, facing East. Photo illustrates the establishment of desirable species (Crested wheatgrass) but there are bare patches which are not reflective of reference areas.

Inspection Photos
Location Name: CORNISH #22-3
Location ID: 305495



Photo 5. Reference photo taken north of the well location, facing East.