



Decommission Input

Site Name: UPRC 33-7F,8F

Site Type PRODUCTION FACILITY	Current Status ABANDONED	Sub Status	Active Site? No	Report Center 10065800
Well Count 2	Production Route SOUTH LTSI 2	Latitude (°)	Longitude (°)	
Access Directions				

Jobs

Job ARO	Job Type COGCC INSPECTION	Major Contractor H-2 ENTERPRISES LLC	Job Start Date 1/10/2023	Job End Date 4/10/2023
Primary Status COMPLETE	<p>Objective UPRC 33-7F (API 123-15422) & 8F Battery Insp Doc #: 697504270 Well Facility ID: 247625 Loc ID: 328006 Insp Photos Doc #: 697504273, http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5889318</p> <p>Comments: This is an Interim Reclamation inspection at the associated tank battery for a well which is part of an AOC (Order No 1V-668). All equipment has been removed from the associated tank battery. It does not appear the Operator has performed reclamation activities at the tank battery location since there was no desirable vegetation observed. The former tank battery area would be considered cropland.</p> <p>Corrective Actions: Perform reclamation in accordance to Rule 1003. Collaborate with the landowner to determine mitigating measures that will allow reclamation work to be conducted in such a manner as to not interfere with agricultural activities or crop production.</p>			

Summary

On April 10, 2023, UPRC 33-7F was deep ripped to a depth of 18-inches, vibrashanked and disced for seedbed preparation, then a drill was used to apply Triple Super fertilizer and cover crop seed. Two bales of certified weed free straw were blown across site then crimped into dirt as a soil stabilization parameter on 0.5 acres (0.3 acres of pad, 0.2 acres of road).

Job Contacts

Name Newby, Abbey [ERM] <abbeynewby@chevron.com>	Title RBU OE-HSE	Mobile Phone 720.833.8814
---	---------------------	------------------------------

Activity Reports

Activity Start Date 1/10/2023	Activity End Date 1/10/2023	Onsite Rep	Activity Site Status	Incident?
Summary H2 collected 2 soil samples to compare onsite soil conditions to offsite soil conditions. Developed reclamation plan.				
Next Planned Activity				

Daily Field Costs

Carry forward?	Cost Description	Task	Line Item	Vendor	Ticket #	Note	Amount (Cost)
Activity Start Date 4/10/2023		Activity End Date 4/10/2023		Onsite Rep		Activity Site Status	Incident?
Summary Rip to 18". Vibrashank and disc. Drill in Triple Super fertilizer and cover crop seed. Blow and crimp-in 2 bales of certified weed free straw. 0.5 acres (0.3 acres pad, 0.2 acres road)							
Next Planned Activity							

Daily Field Costs

Carry forward?	Cost Description	Task	Line Item	Vendor	Ticket #	Note	Amount (Cost)
Yes	Seeding	247038				HUWA/H2 Enterprises; invoice went to Erica Zuniga	5,152.00

Field Cost Summary

Cost Description Seeding	Task 247038	Line Item	Vendor	Sum of Amount (Cost) 5,152.00
Total (Sum)				Sum of Amount (Cost) 5,152.00