

# CAERUS PICEANCE LLC, TEXACO FEE-66S99W/17SWNE

Location # 323831



Location Entrance – Photo #02800



Wellhead – Photo #02802

# CAERUS PICEANCE LLC, TEXACO FEE-66S99W/17SWNE

Location # 323831



Separator – Photo #02801



Tank – Photo #02805

# CAERUS PICEANCE LLC, TEXACO FEE-66S99W/17SWNE

Location # 323831



**Access Road Lacks Stabilization – Photo #02809**



**Insufficient Vehicle Tracking BMPs – Photo #02811**