

Inspection Photos

May 2, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334602

Location Name: CEDAR SPRINGS RANCH-67S93W/11NWSE

Inspection Document #: 702801504

Garfield County, CO

NWSE Section 11 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CEDAR SPRINGS RANCH-67S93W/11NWSE
Location ID: 334602



Photo 1. Photo taken from the east shows an overview of the location.



Inspection Photos

Location Name: CEDAR SPRINGS RANCH-67S93W/11NWSE

Location ID: 334602



Photo 2. Photo shows stained gravel appears to have been cleaned from the tank battery secondary containment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801504

Inspection Photos

Location Name: CEDAR SPRINGS RANCH-67S93W/11NWSE

Location ID: 334602



Photo 3. Photos show list B noxious musk thistle rosettes throughout the northern and eastern interim area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801504

Inspection Photos

Location Name: CEDAR SPRINGS RANCH-67S93W/11NWSE

Location ID: 334602



Photo 4. Photos show interim areas to the north (left) are well vegetated. However, list B noxious musk thistle rosettes were observed throughout.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801504

Inspection Photos

Location Name: CEDAR SPRINGS RANCH-67S93W/11NWSE

Location ID: 334602



Photo 5. Photos show interim areas to the east (left) and south (right) are well vegetated with perennial grasses and shrubs.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801504