

Caerus Piceance LLC
C35
Location # 335359



Location




location



Caerus Piceance LLC
C35
Location # 335359



Location



location



Caerus Piceance LLC
C35
Location # 335359



Cut slope lacks stabilization



Cut slope lacks stabilization



Caerus Piceance LLC
C35
Location # 335359



Cut slope lacks stabilization and another dead horse in interim reclamation



Lack of stabilization/compaction



Caerus Piceance LLC
C35
Location # 335359



Lack of stabilization/compaction



Lack of stabilization/compaction



Caerus Piceance LLC
C35
Location # 335359



Lack of stabilization/compaction



Lack of stabilization/compaction



Caerus Piceance LLC
C35
Location # 335359



Deceased horse on location



Deceased horse on location



Caerus Piceance LLC
C35
Location # 335359



Open for wildlife to enter



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources