

LARAMIE ENERGY LLC, Shell/797-09A

Location #335018



Location – Photo #02815

Wellheads – Photo #02816

LARAMIE ENERGY LLC, Shell/797-09A

Location #335018



Separators – Photo #02827



Tank Battery – Photo #02820

LARAMIE ENERGY LLC, Shell/797-09A

Location #335018



Location Lacks Stabilization – Photo #02824



Location Lacks Stabilization – Photo #02826

LARAMIE ENERGY LLC, Shell/797-09A

Location #335018



Insufficient Stormwater BMP – Photo #02828



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #02830