

LARAMIE ENERGY LLC, CC/0620-43-32 Pad

Location # 335456



Location – Photo #02842



Wellheads – Photo #02840

LARAMIE ENERGY LLC, CC/0620-43-32 Pad

Location # 335456



Separators – Photo #02839



Tank Battery – Photo #02835

LARAMIE ENERGY LLC, CC/0620-43-32 Pad

Location # 335456



Cut Slope Eroding onto Location – Photo #02836

Cut Slope Eroding onto Location – Photo #02838

LARAMIE ENERGY LLC, CC/0620-43-32 Pad

Location # 335456



Cut Slope Eroding onto Location – Photo #02838



Location Lacks Stabilization – Photo #02844

LARAMIE ENERGY LLC, CC/0620-43-32 Pad

Location # 335456



Access Road Lacks Stabilization– Photo #02847



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #02849