

LARAMIE ENERGY LLC, CC/0620-24-43 Pad

Location # 335205



Location – Photo #02861



Wellheads – Photo #02857

LARAMIE ENERGY LLC, CC/0620-24-43 Pad

Location # 335205



Separators – Photo #02856



Tank Battery – Photo #02852



LARAMIE ENERGY LLC, CC/0620-24-43 Pad

Location # 335205



Cut Slope Eroding onto Location – Photo #02854



Cut Slope Eroding onto Location – Photo #02855

LARAMIE ENERGY LLC, CC/0620-24-43 Pad

Location # 335205



Location Lacks Stabilization – Photo #02859



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #02863

LARAMIE ENERGY LLC, CC/0620-24-43 Pad

Location # 335205



Access Road Erosion – Photo #02864



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #02866