

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 534-20 Pad

Location ID: 335295



Photo # 6949 From entrance to location



Photo # 6950 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 534-20 Pad

Location ID: 335295



May 5, 2023 at 8:44:18 AM
CO



May 5, 2023 at 8:44:26 AM
CO

Photo # 6953 Location

Photo # 6954 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 534-20 Pad

Location ID: 335295



Photo # 6955 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 534-20 Pad

Location ID: 335295



Photo # 3933 From Inspection 708900200 conducted on 03/31/2023 Meter calibration info not conspicuously posted

Photo # 6963 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 534-20 Pad

Location ID: 335295



Photo # 3934 From Inspection 708900200 conducted on 03/31/2023 Meter calibration info not conspicuously posted

Photo # 6965 Meter calibration info not conspicuously posted