

LARAMIE ENERGY LLC, CC/0705-22-43 Pad

Location # 335186



Location – Photo #02926




Wellheads – Photo #02927

LARAMIE ENERGY LLC, CC/0705-22-43 Pad

Location # 335186



Separators – Photo #02930



Tank Battery – Photo #02935



LARAMIE ENERGY LLC, CC/0705-22-43 Pad

Location # 335186



Location Lacks Stabilization – Photo #02933



Location Lacks Stabilization – Photo #02938

LARAMIE ENERGY LLC, CC/0705-22-43 Pad

Location # 335186



**Insufficient Vehicle Tracking BMPs at Location
Entrance/Exit – Photo #02960**