

# Interim Reclamation and Stormwater Inspection

Date: 05/03/2023

Operator: FUNDARE RESOURCES OPERATING  
COMPANY LLC - 10773

Location ID: 442134

Inspection Document #: 708200217

Weld County, CO

NWSE Section 30 T10N R58W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Razor 30J Pad  
Location ID: 442134



**Photo 1.** Taken from the eastern portion of the reclaimed area. Photo illustrates that desirable perennial plant species are evident throughout the interim areas. However, portions of the reclaimed areas don't appear to be progressing towards Rule 1003 standards with evidence of non-uniform vegetation cover resulting in areas of bare soil, highlighted in red.



Inspection Photos  
Location Name: Razor 30J Pad  
Location ID: 442134



**Photo 2.** Taken from the northern portion of the reclaimed areas; see comments in Photo 1.



Inspection Photos  
Location Name: Razor 30J Pad  
Location ID: 442134



**Photo 3.** Taken from the western portion of the reclaimed areas; see comments in Photo 1.



Inspection Photos  
Location Name: Razor 30J Pad  
Location ID: 442134



**Photo 4.** Taken from the southern portion of the reclaimed areas; see comments in Photo 1.



Inspection Photos  
Location Name: Razor 30J Pad  
Location ID: 442134



**Photo 5.** Example of russian thistle observed within the production area. Undesirable plant species will need to be properly managed for during the next local growing season.



Inspection Photos  
Location Name: Razor 30J Pad  
Location ID: 442134



**Photos 6 & 7.** Unknown fluid observed pooling on top of the secondary containment will need to be properly cleaned up/disposed of. Also pictured, tank label that is peeling, faded, and cracked; label/placard will need to be replaced.