

# LARAMIE ENERGY LLC, CC/0620-01 Pad

Location # 335190



**NW Corner of Location– Photo #02965**



**NE Corner of Location – Photo #02967**



# LARAMIE ENERGY LLC, CC/0620-01 Pad

Location # 335190



SW Corner of Location – Photo #02964



SE Corner of Location – Photo #02970



# LARAMIE ENERGY LLC, CC/0620-01 Pad

Location # 335190



Wellheads – Photo #02968



Separators – Photo #02971



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



# LARAMIE ENERGY LLC, CC/0620-01 Pad

Location # 335190



**Tank Battery – Photo #02974**



**Location Lacks Stabilization – Photo #02966**

# LARAMIE ENERGY LLC, CC/0620-01 Pad

Location # 335190



**Insufficient Vehicle Tracking BMPs at Location  
Entrance/Exit – Photo #02977**