

Inspection Photos
Location Name: Wind #1
Location ID: 319057



Photo 1: Tank Battery Sign



Photo 2: Appears to have sold product

Inspection Photos
Location Name: Wind #1
Location ID: 319057




Photo 3: Appears to have sold product



Photo 4: Valves appear to be open

Inspection Photos
Location Name: Wind #1
Location ID: 319057



Photo 5: Valves appear to be open



Photo 6: Valve appears to be open

Inspection Photos
Location Name: Wind #1
Location ID: 319057



Photo 7: Valve appears to be open, pressure present on gauge



Photo 8: Valve appears to be open

Inspection Photos
Location Name: Wind #1
Location ID: 319057



Photo 9: Valves appear to be open, pressure present on gauges