

Inspection Photos
Location Name: Lost Creek 16-29
Location ID: 465199




Photo 1 – Gas Calibration Card



Photo 2 – Appears to have Gas Flowing through Sales Meter

Inspection Photos
Location Name: Lost Creek 16-29
Location ID: 465199



Photo 3 – Yesterday Volume – 23.4 MCF



Photo 4 – ECD and Separator

Inspection Photos
Location Name: Lost Creek 16-29
Location ID: 465199



Photo 5 – Tank Battery



Photo 6 – Tank Battery Sign

Inspection Photos
Location Name: Lost Creek 16-29
Location ID: 465199



Photo 7 – Produced Water Tank



Photo 8 – Crude Oil Tank

Inspection Photos
Location Name: Lost Creek 16-29
Location ID: 465199



Photo 9 – Unmarked Risers in Tank Berm