

Inspection Photos

5/8/2023

Operator: UTAH GAS OP LTD DBA UTAH GAS
CORP - 10539

Location Number: 322479
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location Number: 322479



Photo 1: Photo taken from the access road, adjacent to Road 201. Photo shows stormwater and erosion control BMPs to stabilize, as well as to minimizes erosion, transport of sediment, and degradation remain missing or insufficient at the access road; erosion degradation has persisted.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location Number: 322479



Photo 2: See comments under photo 1. 6 Foot measuring stick for reference.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location Number: 322479



Photo 3: See comments under photo 1. 6 Foot measuring stick for reference.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location Number: 322479



Photo 4: See comments under photo 1. 6 Foot measuring stick for reference.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location Number: 322479



Photo 5: See comments under photo 1.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location Number: 322479



Photo 6: Photo taken from the east of culverts/former stream crossing along the access road. Photo shows stormwater and erosion control BMPs remain missing or insufficient; access road has not been maintained and lacks a properly engineered stream crossing. Salt Creek is actively flowing; flows are now channeled east of where the culverts and the former stream crossing are located (arrow), resulting in erosion degradation to the access road and additional sediment discharges into Salt Creek.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location Number: 322479



Photo 7: See comments under photo 6.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location Number: 322479



Photo 8: See comments under photo 6.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location Number: 322479



Photo 9: See comments under photo 6. 6 foot measuring stick for reference.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location Number: 322479



Photo 10: Photo shows culverts and the former stream crossing. Flows are now channeled east of where the culverts and the former stream crossing are located, resulting in erosion degradation to the access road and additional sediment discharges into Salt Creek.