

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC POTTER-66S95W /36NWNE

Location ID: 335172



Photo #9905 From entrance to location.



Photo #9906 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC POTTER-66S95W /36NWNE

Location ID: 335172



Photo #9907 Loadline open ended.



Photo #9908 Tank label weathered and not legible.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC POTTER-66S95W /36NWNE

Location ID: 335172



Photo #9905 Calibration cards not conspicuously posted.